

銲接轉位器.




3 Tons

銲接轉位器







3 Tons
銲接轉位器

3 Tons 銲接轉位器

可改成油壓驅動上/下調整.









H830 变频器
考展

MITSUBISHI
5800 FUJI MOLD PUMP
PU EXT SET
MODE SET
E700
39400V

NOZZ
SIEMENS
Red indicator lights

14
SIEMENS
BA-1000 TYPE CONTROLLING TRANSFORMER
Input Voltage: 220V
Output Capacity: 50VA
Date: 2011.11.11

Terminal block with multiple wires







1.2 Tons

銲接轉位器









銲接轉位器:設備規範.

主要技术参数 Main Technical Parameters

规格型号 Model	额定承载 Rated loading (kg)	回转速度 Speed of table (rpm)	翻转速度 Overturning velocity (rpm)	翻转角度 Overturning angle (°)	工作台尺寸 Size of work table(mm)	电机功率 Power(kw)		调速方式 Way of setting	额定载荷 时最大偏 心距 Max eccentric distance (mm)	额定载荷 时最大重 心距 Max distance of gravity center(mm)	垂直平面 回转直径 Max turning diameter (mm)
						回转 Turning	翻转 Overturning				
ZHBJ-01	100	0.4-4	手动 By hand	0-120	φ400	0.18	/	变频无级调速 variable frequency drive	100	200	φ400
ZHBJ-03	300	0.1-1	手动 By hand	0-90	φ600	0.18	/		150	200	φ800
ZHBJ-03	300	0.1-1	1	0-90	φ600	0.18	0.18		150	200	φ800
ZHBJ-06	600	0.09-.0.9	1	0-90	φ1000	0.75	0.75		150	200	φ1500
ZHBJ-12	1200	0.05-0.5	0.4	0-120	φ1200	1.1	1.1		200	250	φ2050
ZHBJ-30	3000	0.05-0.5	0.23	0-135	φ1400	1.5	2.2		200	300	φ2100
ZHBJ-50	5000	0.05-0.5	0.2	0-135	φ1500	2.2	3		200	300	φ2500
ZHBJ-100	10000	0.05-0.5	0.2	0-135	φ2000	3	4		200	400	φ3240
ZHBJ-200	20000	0.05-0.5	0.2	0-135	φ2000	3	4		200	400	φ3240

電動驅動上/下盤面
位置調整。

伺服馬達驅動盤面旋轉。



